

Excess Tools Part List & Accessories Declaration Form

Transaction Type : Retirement for Sale/Trade In/Scrap/Intercompany/Temporary Storage
Tool ID : CVD4350
Date : 27-08-2018

a. General

Cat	Description
Vendor / Supplier	ASM Japan
Model	XP8
Process	PEALD HT SIO; PEALD LT SIO;
Vintage (Year of Manufacture)	
Serial No.	30FE.1948
Asset Description	ASM Europe B.V. EAGLE XP8 [PE-ALD OXIDE]
Tool Status	Unhooked
Software Version	
CIM	

b. Hardware Configuration (Fab)

Cat	Description	Qty / Units	Status
Main System	central platform w/ load lock	1	
	DCM (dual chamber module) HT-SIO	2	
	DCM (dual chamber module) LT-SIO	1	
SMIF System	loadports "TDK TA300"	3	
Handler System	dual blade robot	1	
Options	Frontside Option only		
Others (Pls specify if any)	n/a		

c. Hardware Configuration (Subfab / Auxilliary Units)

Sub Accessories / Auxilliary Units	Qty / Units	Status
DTLR Versum/ Schumacher CG200	1	not used
Pump "EV-S20P, 400V"	1	not used
Pump "EV-S100P, 400V"	1	not used
Pump "EV-M302N-BE, 400V"	3	missing, not in pump rack
Abatement CT-Centrotherm	1	not used
Power Rack	1	warehouse

d. Missing/Faulty Parts / Accesories List

(If NO missing/faulty parts/accessories please indicate NA)

Description	Qty / Units
n/a	
Total Estimated USD	

Tool Photos (Photos must make sense to show all the major parts intact)

Tool ID : CVD4350
Date : 27-08-2018

a. General

Description	Photos
Eqpt ID	n/a - currently crated and in the warehouse
Vendor / Supplier / Model INCLUDE A PHOTO OF THE SERIAL NUMBER TAG THAT IS AFFIXED TO THE TOOL.	n/a - currently crated and in the warehouse

b. Hardware Configuration (Fab)

Description	Photos
Main System	n/a - currently crated and in the warehouse
SMIF System	n/a - currently crated and in the warehouse
Handler System	n/a - currently crated and in the warehouse
Chambers	n/a - currently crated and in the warehouse
Others	n/a - currently crated and in the warehouse

c. Hardware Configuration (Subfab / Auxilliary Units)

Description	Photos
	n/a - currently crated and in the warehouse

d. Missing Parts [photos showing major missing parts]

Description	Photos
	n/a - currently crated and in the warehouse

